## REPORT

## TRUESDAIL LABORATORIES, INC.

## CHEMISTS - MICROBIOLOGISTS - ENGINEERS RESEARCH - DEVELOPMENT - TESTING

ESTABLISHED 1931



14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 (714) 730-6239 • (213) 225-1564 FAX (714) 730-6462

CLIENT:

Douglas Aircraft Company

Internal Mail Code 9-20

3855 Lakewood Blvd.

Long Beach, CA 90846

ATTN:

Scott Lattimore

**SAMPLE DATE:** 01/04/95

PERMIT NUMBER: NPDES # CA0001414 SITE I.D. Torrance Stormdrain

By Site #799

REPORT DATE: Jan. 19, 1995

RECEIVED: Jan. 04, 1995

LABORATORY NUMBER: 77424

Monthly Analysis as Requested

## RESULTS

pH, Units (150.1)

mperature, OF


Flows

6.97

56

No Flow

\*ND = Not detected, below detection limit



Respectfully Submitted, Truesdail Laboratories, Inc.

Thomas Herrin, Manager

Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising of publicity matter without prior written authorization from these Laboratories.